


Eclipse Veri-Flame Single Burner Monitoring System

Spare Parts List 818

1/15/2015

Version 1



Category	Ref	Part Number	Description	Model Number
Sensors	1	49600-91	Straight UV Scanner	5600-91
	5	20898	NEMA 4 UV Scanner	5600-91N4
	2	49600-90	90° UV Scanner	5600-90A
	4	49602-91	Self Check Scanner	5602-91
	-	49602-91-7	10-Foot Cable for Self Check Scanner	5602-91-7
	6	20722	Scanner Support (1)	5600-90A SS
	7	49600-98	Magnifying Lens Assembly	5600-98
	-	49600-99	Magnifying Lens (2)	
	-	18165	Non-Magnifying Lens (2)	
	8	49099	Insulated Coupling	5600-99
	-	21741	Coax Cable, R62A/U for Flame Rod	
	-	400011	Heat Block Seal	23 HBS
Bases	9	22194	Internal Terminal Base, Plastic	5602-10-P
	10	22195	Exposed Terminal Bas, Plastic	5602-10-1P
	11	49602-40	Modulation Base	5602-40
	-	22110	Mounting Screw to Plastic Base	
Test	-	49602	Tester for Veri-Flame Units	5602
	-	49240-2	Relay Module (3)	5602-40-4
Display	-	20896	Remote Display, 120 VAC with keypad	5602 DBP
	-	20318	Cable for Remote Display	